

VEHICLE INSPECTION REPORT

W6587

STIHL BR600 BACK PACK LEAF BLOWER

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

DONCASTER STIHL BR600 BACK PACK LEAF BLOWER, YR 2019 *PULLS DOES NOT START*

Reg. date	Mileage	TBC	Colour
Year	Fuel Type	VIN	
2019			

Tyres
NSF
NSR
OSF
OSR
Spare

Photos

